Security Advisory

Published on: September 07, 2022

CVE	CVE-2022-32966
Title	TCP Port 5900 is open for connection without valid credentials. The unauthorized connection will fail as described below.
Description	When connecting to TCP port 5900 of the RTL8111FP with KVM enabled DASH system, the system would reboot to a black screen. The system will not work until you disconnect the power supply to the system and then power it on again with credentialed access.
Severity	High
CVSSv3	CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:C/C:L/I:N/A:H
Vulnerability Type	Denial of Service
CWE	CWE-863
Affected Chipsets	RTL8111FP
Affected Software Versions	Firmware version before 5.0.23

Acknowledgement

The Realtek Production Security Team would like to thank the following people and parties for finding and responsibly reporting security vulnerabilities to improve Realtek production security.

● Blake Irwin <mirwin@lenovo.com>, Lenovo

# # #